

## Profiles in patient safety: misplaced femoral line guidewire and multiple failures to detect the foreign body on chest radiography.

June 23, 2009

Lum TE, Fairbanks RJ, Pennington EC, et al. Profiles in Patient Safety: Misplaced Femoral Line Guidewire and Multiple Failures to Detect the Foreign Body on Chest Radiography. Acad Emerg Med. 2005;12(7):658-662. doi:10.1197/j.aem.2005.02.014.

https://psnet.ahrq.gov/issue/profiles-patient-safety-misplaced-femoral-line-guidewire-and-multiple-failures-detect-foreign

Using a case report, the authors discuss a series of errors and illustrate the concepts of <u>active</u> and <u>latent</u> <u>failures</u>. They suggest systems-oriented improvements to both the technique and catheter kit used.